SEPTIC

Township of Ramara

Building Inspection Department

REPORT OF INSPECTION

P.O. Box 130
Brechin, Ontario
L0K 1B0
Phone (705) 484-5374
Fax (705) 484-0441

PERMIT NO. 3051 October 21, 2002 TIME ..... A.M. / P.M. DATE Nov. 8 20 02

TO: Carter, Steve
7869 OAKRIDGE DR

ADDRESS: RR#1, Washago, Ontario L0K 2B0

INSPECTION REQUESTED: Septic

LOCATION: Plan 262; Lot 22

No Apparent Infraction at Time of Inspection ..... Bob GIBSON
Inspector.

TAKE NOTICE: that you are required to comply with the following Order(s)

ORDER No.	
	COMPLETED -

Order No.(s) ..... shall be carried out forthwith and reinspected.

Order No.(s) ..... shall be carried out on or before .....
and reinspected.

A request for reinspection is required. Yes ☐ No ☑

..... INSPECTOR

REPORTED RECEIVED BY:

.....

EMPLOYER .....

4964