



Township of Algonquin Highlands
Building Department
 1123 North Shore Road
 Algonquin Highlands, Ontario
 K0M 1J1



WSP Canada Inc.
Septic Re-Inspection Project Team
 126 Don Hillock Drive, Unit 2
 Aurora, Ontario
 L4G 0G9

*Cottrell
 Septic Inspection
 June 2018
 AOKAY*

DOROTHY JUNE ZIEGLER
 114 MARKSAM ROAD

GUELPH ON
 N1H 6T4

June 18, 2018

Re: Township of Algonquin Highlands - Septic System Re-Inspection Program
1100 Sonora Dr
 Inspection Results

Dear Property Owner,

Please find enclosed the results of your septic system survey.

If you have any questions or concerns regarding the results do not hesitate to contact me.

Sincerely,

WSP Canada Inc.

Kathryn Stasiuk, EIT | Project Coordinator
 Individual BCIN # 102501, WSP BCIN # 39534
 ah.info@wsp.com | www.wsp.com
 1-289-984-0432

KSR:nah



Township of Algonquin Highlands
Building Department
 1123 North Shore Road
 Algonquin Highlands, Ontario
 K0M 1J1



WSP Canada Inc.
Septic Re-Inspection Project Team
 126 Don Hillock Drive, Unit 2
 Aurora, Ontario
 L4G 0G9

*Cottrell
 Septic Inspection
 June 2018
 AOKAY*

DOROTHY JUNE ZIEGLER
 114 MARKSAM ROAD

GUELPH ON
 N1H 6T4

June 18, 2018

Re: Township of Algonquin Highlands - Septic System Re-Inspection Program
1100 Sonora Dr
 Inspection Results

Dear Property Owner,

Please find enclosed the results of your septic system survey.

If you have any questions or concerns regarding the results do not hesitate to contact me.

Sincerely,

WSP Canada Inc.

Kathryn Stasiuk, EIT | Project Coordinator
 Individual BCIN # 102501, WSP BCIN # 39534
 ah.info@wsp.com | www.wsp.com
 1-289-984-0432

KSR:nah



Township of Algonquin Highlands
Building Department
 1123 North Shore Road
 Algonquin Highlands, Ontario
 K0M 1J1



WSP Canada Inc.
Septic Re-Inspection Project Team
 126 Don Hillock Drive, Unit 2
 Aurora, Ontario
 L4G 0G9

*Cottrell
 Septic Inspection
 June 2018
 AOKAY*

DOROTHY JUNE ZIEGLER
 114 MARKSAM ROAD

GUELPH ON
 N1H 6T4

June 18, 2018

Re: Township of Algonquin Highlands - Septic System Re-Inspection Program
1100 Sonora Dr
 Inspection Results

Dear Property Owner,

Please find enclosed the results of your septic system survey.

If you have any questions or concerns regarding the results do not hesitate to contact me.

Sincerely,

WSP Canada Inc.

Kathryn Stasiuk, EIT | Project Coordinator
 Individual BCIN # 102501, WSP BCIN # 39534
 ah.info@wsp.com | www.wsp.com
 1-289-984-0432

KSR:nah